

TOKHEIM GUIDED FLOAT KIT

On new tanks weld ¾” couplings in tank roof in a vertical position, locating them as shown in Print No. 215 using the center coupling for gauge connection.

Cable tighteners as shown in Print No. 232 in the other two couplings welded in tank roof.

Weld cable anchors as shown in Print No. 233 to bottom of tank positioning them directly under cable tighteners (use plumb bob).

Cables furnished are 27 strand 18 – 8 Stainless Steel.

Floats are equipped with a Stainless Steel band holding two substantial S.S. blocks with holes drilled for guide cables.

Cables are secured to cable tighteners with Stainless Steel cable clamps on Print No. 232.

When ordering specify sidewall height of tank.